

Work Order ID 73152

Friday, August 26, 2011 7:01:56 AM



Page 1

Item ID: D350-561-143

Accept



Setup Start



Revision ID:

Stop



Item Name: Dual Cargo Mirror Installation, RH

Start Date: 8/26/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 9/9/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: CL Date: 11/08/24 Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D350-561

Rev D

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D350-561-143 CHG003

11/10/28
H for BG 11-9-13

105

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

11/9/12

110

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

11/10/28

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73152

Friday, August 26, 2011 7:01:57 AM



Page 2

Item ID: D350-561-143

Accept



Setup Start



Revision ID:

Item Name: Dual Cargo Mirror Installation, RH

Stop



Start Date: 8/26/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 9/9/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	Packaging	0.00							
	Packaging								
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D350-561-143								
	C								
130	QC21- Final Inspection - Work Order Release	0.00							
	QC								
Quality Control	Memo	0.00							

44/10/28

11/10/28
-mf
11-10-28

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Friday, August 26, 2011 7:01:53 AM

Page 1

1. The first step in the process is to identify the problem. This involves gathering information about the situation and the people involved.

2. The second step is to analyze the problem. This involves breaking the problem down into its components and identifying the underlying causes.

3. The third step is to develop a plan. This involves determining the steps that need to be taken to solve the problem.



4. The fourth step is to implement the plan. This involves putting the plan into action and monitoring progress.

5. The fifth step is to evaluate the results. This involves assessing the effectiveness of the solution and making adjustments as needed.

[illegible]

Required Qty: 2.00

Comments: IPP A 07.07.26 new issue (DSI9379) EC verified by:JLM IPP rev
B 10.02.16 per ecn 10-523 EC verified by: DD□

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D350-561-045  Dual Mirror Accessory Installation		Manufactured	No			105	Each	1.0000	1	2			
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				FG041		1							
					70547	1							
D350-561-141  Single Cargo Mirror Installation, RH		Manufactured	No			105	Each	0.0000	1	2			

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

5. PARTS LIST

Qty -041	Qty -043	Qty -045	Qty -141	Qty -143	Part Number	Description
X	1				D350-561-041	SINGLE MIRROR INSTALLATION
	X				D350-561-043	DUAL MIRROR INSTALLATION
	1	X		1	D350-561-045	MIRROR KIT
			X	1	D350-561-141	SINGLE MIRROR INSTALLATION
				X	D350-561-143	DUAL MIRROR INSTALLATION
1		1	1		D2011-101	Mirror
1					D2012-101	Arm
1					D2012-103	Arm
1			1		D2012-105	Arm
2			1		D2012-107	Clevis
1					D2012-109	Bracket
1			1		D2012-111	Bracket
4		2			D2012-113	Clamp
1			1		D2012-115	Bracket
4			2		D2022-101	Spacer
4					D2856-100-325	Abrasion Strip
1*		1*	1*		D3014-1	Locknut
			1		D3629-1	Bracket
			1		D3635-1	Gasket
		2			D3635-3	Gasket
			1		D3646-1	Arm
			1		D3646-3	Arm
			2		D4070-041	Clamp
2		2	3		AN3-4A	Bolt
2			3		AN3-5A	Bolt
1			1		AN3-6A	Bolt
2			1		AN4-10A	Bolt
3			3		AN4-5A	Bolt
14		4	8		AN960JD10	Washer
9		2	8		AN960JD416	Washer
1*		1*	1*		AN960JD416L	Washer
5		2	4		MS21042L3	Nut (or MS21042-3)
5			4		MS21042L4	Nut (or MS21042-4)

*INCLUDED AS PART OF D2011-101 MIRROR